



The P point is cross of J5 and J6 axis.






View A (Scale 1:4)




### Detail of base fixture

View B (Scale 1:4)



Detail E (1:1)



The orientation in this drawing is  
90° for J3 only and 0° for other axes.

Scale 1:15

TVMI 500

|                            |           |
|----------------------------|-----------|
| SHIBAURA MACHINE Co., Ltd. | S-2NN21-2 |
|----------------------------|-----------|